
Dec – Jan Winter Storms

1

Agenda

- Preparedness
- Response
- Damages
- Recovery



Preparedness

Challenges

- Staff Turnover Loss of historic and institutional knowledge
- Flood/Drought Cycle
 - Extended time between floods/highwater events
- Multiple Agencies
 - Coordinated Operations & Communications

Opportunities

- Updates to
 - Emergency Operations Plans,
 - Flood Contingency Maps,
 - Regional Flood Management Plans,
 - · Stream and Rain Gage Networks,
 - Prepositioned Flood Fight Materials, and
 - GIS Framework

3

Preparedness

Previous Preparedness Efforts

- Lower San Joaquin River RFMP
- Delta FERP Grant Round 1
 - Updates to EOP, Flood Contingency Maps (FCM), Training, Pre-staged material
- Statewide FERP Grants 1 & 2
 - Updates to EOP, FCMs, Training, Pre-staged materials
- Levee and channel maintenance
- USACE Periodic Inspections
- DWR levee inspections
- Multi-county, Delta-wide flood training exercise (November 2022)

Δ

Preparedness

Ongoing/Upcoming Preparedness Efforts


- Delta FERP Grant Round 2 & 3
 - Updates to EOP, FCM, Flood Warning System
- Statewide FERP Grant Round 3
 - Updates to EOP, FCMs, Flood Warning System, GIS Tools
- Lower San Joaquin River RFMP
- Ongoing Levee & Channel Maintenance Program
- USACE Rehabilitation Program (PL 84-99)
- FOC/SJ River Basin Coordination

5

Flood Emergency Response

Emergency Roles

- Monitoring & Analyses
 - Water Conditions, Elevations, & Forecasts
 - Identification of heightened threats to levee & drainage system integrity
- Flood Fight Operations
 - Levee patrols
 - Emergency Repairs
 - Erosion
 - Seepage
 - Downed trees
- Engineering Support
 - Responding to public response
 - · Coordinating with Ops
 - Tracking, documentation, and assessments



Dec-Jan Storm Damages Mormon Slough

- Erosion
- Slips



7

Dec-Jan Storm Damages

Mormon Slough

- Landside overtopping
- Upstream of Duncan Rd



Dec-Jan Storm Damages

Calaveras River

- Downed trees



9

Dec-Jan Storm Damages

Potter Creek

- Bank slippage
- Upstream of Duncan Rd



Interior/Local Drainage Acampo



Photo credit: Lodinews.com

11




Photo credit: Glenn Moore/Tracy Press


Interior/Local Drainage
Littlejohn Creek




13

Damages/Recovery

- Overall Damages for Public Works (includes Roads & Utilities)
 - Approximately \$30.1M
- Damagers for SJCFCWCD's Channels and Levees
 - Approximately \$26M
 - Majority of which is to Federal Projects (Mormon Slough alone is ~\$21M)
- Does <u>not</u> include economic impacts





Next Steps

- Continue pursuing both FEMA & USACE dollars to assist in damage recovery
- Continue working with State partners for identifying potential solutions for Acampo flooding
- Update Corral Hollow Feasibility Study
- Develop projects/prepare for upcoming HMGP Grant opportunities
- Delta 2/Statewide 3
 - Update EOPs
 - Update FCMs
 - Update/enhance flood warning system
- Document lessons learned
- Training
- Continued Coordination w/ State & Feds for Snowmelt

Challenges

- PL 84-99 not opened by USACE yet
- PL 84-99 / Public Assistance Timing mismatch
- Lingering damages from 2017
- Looming snowmelt

17

Backup

